

These articles and information is brought to you by The 1937 and 1938 Buicks Club. For more information please contact us at:

http://autos.groups.yahoo.com/group/1937and1938Buicks/ or WWW.1937and1938Buicks.com

-- Warning Notice --

It the mission and goal of 1937 and 1938 Buicks Club is to provide information, helpful hints, advice, directions and reference information for the repair, maintenance, authentic restoration and knowledge development in regards to 1937 and 1938 Buick's. Content is offered as informational only.


The 1937 and 1938 Buicks Club does not knowingly accept false or misleading content or advertising. Nor does The 1937 and 1938 Buicks Club assume any responsibility for the consequences that may occur should any such material appear.

The 1937 and 1938 Buicks Club does not guarantee the quality of any information which is included in this or any other publication. Under no circumstances shall The 1937 and 1938 Buicks Club be liable for any damages, losses, or injuries resulting from use reliance on the content of this or any other publication. Any reliance on this or any other publication content is at your own risk.

As a precautionary measure, The 1937 and 1938 Buicks Club strongly recommends that you contact a professional mechanic or restoration shop to check your work or answer specific questions.

-- Copyright Notice --

All rights reserved. All documents and publications on The 1937 and 1938 Buicks Club web site or that can be down loaded from The 1937 and 1938 Buicks Club web site are protected under both U.S. Federal copyright law and international treaties. No component of this site, including text, images and computer code, may not be reproduced or copied in any form or by any means--electronic, graphic, digital or mechanical, including photocopying or information storage & retrieval systems--without the express prior written permission of The 1937 and 1938 Buicks Club.



TORQUE TUBE

THE NEWS PUBLICATION FOR MEMBERS OF THE 1937-1938 BUICK CLUB



VOLUMN XV · NUMBER 2 · NOVEMBER / DECEMBER 1996

BUICK 1937 **U** 1938

TORQUE TUBE

THE NEWS PUBLICATION FOR MEMBERS OF THE 1937-1938 BUICK CLUB

VOLUMN XV · NUMBER 2 · NOVEMBER / DECEMBER 1996

THE 9th CYLINDER BY HARRY LOGAN #651, Editor

Season's Greeting and Best Wishes for 1997 to all our members. I hope you received a present like this one on Christmas Day.

This is the November/December issue, the second of our 1996-1997 publishing year. Our membership has dropped about a hundred. We now have over 400 members compared to over 500 last August. Hopefully many of

did not renew will rejoin us after I mail them a reminder letter in January.

the members who

Waggoner (#10) and I have been publishing this award winning magazine. Since the founding of the Club, Dug has been providing Dave Lewis and Bill Olson with illustrations and other graphics needed to help produce the Newsletter. One of the first items Dug produced was our '37-'38 Buick Club emblem. He also produced the masthead for our magazine.

Hopefully we can continue on for a few more years and then pass it along to another member(s). The red 1938 Century woody (top of page 2) was photographed at the 18th annual Meadow Brook Concourse last summer. Meadow Brook was the mansion of

Mathilda Dodge Wilson and her husband. She previously had been married to one of the Dodge Brothers and inherited his wealth when he died and used it to build this home for her and her new husband.

It's located in Rochester, MI.

The red woody has a body by Joseph Wildanger of Red Bank, NJ His son Ed Wildanger now lives about a mile away from me here in Los Altos, CA. He remembers these old woodies from when he was a child sweeping up his father's shop. Ed is now the owner of a furniture factory and showroom featuring custom made European style furniture.

The '38 woody was restored in St. Louis a few years ago and was shown at the 1990 BCA Nationals. The car was also featured in the Bugle magazine. It's now owned by Dick Kughn of Dearborn, ML, the CEO of the Lionel Corp.







Here's another '38 woody below. This one is based on a Roadmaster and was designed

and built by **Jim Pascoe** (#881). It's our cover car and is featured on page 10 of this is-

sue.

I've just become aware of
how expensive it
is for our overseas
members to
purchase dollar
checks in order to
renew their Club
membership.
Mick Whiting


(#381) tells me it costs him \$10 Australian dol-

lars just to buy a US dollar check. I have received several overseas membership renewals

with cash (US currency) in a separate envelope inside the letter. Others have sent cash but registered the letter. Hopefully regis-

check. So far we've never lost a letter.

Gerald Pagano (#961) owns a 1937 Spe-



black on both sides. Then the outside of the



cial Sedan that his grandfather bought new. The car was manufactured at the Linden. New Jersey assembly plant where Gerald now works. Gerald says Buick still paints the firewall data plate body color just as they did in '37 and '38. Gerald says the rims are

ne outside of the rim is painted body color, with black on the inside. This is how the original '37 & '38's I've seen were painted. But one of our members has an original 38-40C with red rims on both sides. Another Buick mystery.

This light

tering a letter is cheaper than buying a dollar gray '38 Special Coupe is owned by non mem-

= TORQUE TUBE=

The TORQUE TUBE is published bi-monthly for the enjoyment of the 1937-1938 Buick Club. Membership dues are \$34.00 per year US, \$35.00 per year Canada and \$40.00 per year for all others. All issues mailed First Class and Overseas issues are mailed Air Mail-Printed Matter unless Surface Mail, at \$35.00 per year, is requested. All memberships run September 1 to August 31 of the following year. Persons joining during the year will receive all back issues from September 1. All payments must be in U.S. funds. Please make your check payable to the 1937-1938 Buick Club.

Please send all articles, ads subscriptions and inquires, etc. to:

THE TORQUE TUBE 1005 RILMA LANE LOS ALTOS, CA 94022 USA

Editor......Harry Logan, #651
Art Director.....Dug Waggoner, #10

YOU CAN REACH HARRY LOGAN by PHONE/FAX (415) 941-4587

or by E-mail: harrylogan@earthlink.net

Printer Liaison......Bill Olson, #427
Printer......Conrads Printing, Lancaster, Ohio

All rights reserved. No part of this newsletter may be reproduced in any form without written permission from THE TORQUE TUBE.

ber Darels Johnson. **Andy Diem** (#852) photograph it at Hershey, PA last October. It was part of the Hundred Years of the American Automobile display sponsored by the Antique Automobile Association (AACA).

Here's **Doug**Nelson (#51) and
his black '38 Century Sport Coupe
in front of his
home in Salem,
Oregon. I recently
visited Doug
while on a trip to
Oregon. Doug has
several garages
behind his house

that are home to his 40 or so old cars.

One of these is a '38 Century Convertible

Coupe Model 66C that is under restoration (bottom photo).

Member Ian Milburn (#1223) phoned me from Bedfordshire, England a few weeks ago to get information on the Club. He has

since joined. Ian owns a Fisher bodied 1938 Special Sedan Model 41.

lan says: "I am really pleased with the Buick. It's probably the best car I ever bought in

terms of value for the money and great to drive. Quite a bit of its enchantment is the fact it's only done 40,900 miles and is quite original. One of the other aspects that interests me is that the front suspension

was designed and developed by Maurice Olley, a Brit. He left Rolls Royce when the Springfield, MA. plant closed to join Cadillac to become a specialist chassis engineer. I know the Buick was developed later but for a big car on old cross ply tires, the '38 still handles well. I started out collecting Ford V8's, so perhaps the comparisons are unfair. But in many ways the Buick is more than a match for

my 1935 3 1/2 litre Bentley."

Members, do you need a new Buick brake drum? Classic Buicks Inc., 4632 Riverside Dr., Chino, CA. 91710 wrote that they have a limited supply of new

brake drums for most model Buicks for the years 1936 through 1970. For information call

them between 8 AM and 5 PM PST Monday-Friday at (909) 591-0238. They are the factory authorized distributor for these USA made products.

And listen to this.....we now have an index of

technical articles published in the *Torque Tube* for the past fifteen years thanks to *Russ Kaufmann* (#303) in Santa Rosa, CA. Russ sent me a copy and I have used it several times al-

ready. What a big help, now I don't have to go looking through a stack of Torque Tubes to find the technical article I want. Thank you very much Russ!

Russ is making this list available to any per-

son who may find it useful. He will send this 15 page list to anyone with a USA address for \$2.50 in stamps. If a copy of an article is required, he will photocopy the article for ten





cents a page provided he has the time.

His address is: Russ Kaufmann (#303), P.O. Box 3761 Santa Rosa, CA, 95402

In the July/August issue, **Bill Whyte** (#968) in Scotland wrote that he was watching the

Australian program Neighbours when he spotted a black '38 Special sedan. Actually the car is Geoff Hilliard's (#698) 1938 Century 4-Dr. Sedan with sidemounts. Geoff lives near Melbourne. His son-in-law arranged to supply the car for this program, which is very popular in the U.K.



New member Leo Gilbert (#1219) in Port Angeles, WA. sent this photo of his 1937 Spe-

cial 4-Door Slant Back Sedan Model 47. Buick made just over 22,000 of this model.

Leo says his car is fully restored and licensed for highway use with the original 1937 plates.

(Ed. I remember the 37-47 well because my best friend had one. This photo of me and the car was taken in 1949 in Pasadena, CA. For some reason, the original paint was wearing thin on each side of the car just above the trunk lid).

New member Phil Mares (#1211) in Midwest City, Oklahoma

has been restoring a '38 Special Trunk Back Sedan Model 41 for the past two years. He has overhauled the engine and had the seats redone. He is now working on the body.

Welcome to the Club Phil.

Walt Morrison (#1092) in Canada writes: "I always look forward to receiving the Torque Tube which always has such interesting information and ideas in it." Thanks Walt and thanks

> to all the members who have sent in information. I've saved it all and will use it in future issues.

D. Hugh Morris (#322) in San Antonio, TX writes that he is in the middle of restoring a sidemounted '38 Century Convertible Coupe that he used to drive years ago. He

hasn't been making much progress on his restoration because he's tied up remodeling an old home with a 4 car garage.

> José Garcia-Menendez (#856) writes: "Here is my renewal check for another year enjoying your friendship, the eagerly awaited Torque Tube and our common love for '37 and '38 Buicks."

This photo (at the top of page 5) of Charlie Ross's (#1015) 1937 Century 4-Door Trunk Back Sedan and a P-51 Mustang was taken at the Quonset, RI Air Museum's Wings of History Air Show. Charlie's car would have been just a few years old when P-51's like this one were fly-

ing over Europe in W.W.II.

This next photo shows Charlie's 37-61 and another W.W.II fighter plane, the US Navy's F4-U Corsair. The Quonset Air Museum used



to be the Quonset Naval Air Station until about 20 years ago. At that time a group of aviation

enthusiasts formed the Air Museum and got an old hanger from the State of Rhode Island. They have been collecting and restoring aircraft ever since. Every year they run a car show and an air show to help

raise money for the museum.

When I got discharged from the US Navy

after the Korean War, I flew home to California in a 2 seat W.W.II fighter plane from Quonset. I was seated behind the pilot in my wool Navy blue uniform. Sitting with the plastic canopy overhead is like being in a green-

house. Boy was I in need of a shower when I finally arrived home.

Jerry Barton (#281) in WA. writes that he put sealer in his gas tank. The tank sat for

about a year before he was ready
to install it. Upon
inspection, he
found the sealer
had settled in the
bottom of the
tank. It was all
cracked and had
partially peeled
off of the sides. A
friend suggested
using acetone to

clean the tank. Jerry put in two gallons (8 liters) and left it in for about a week, turning the tank daily. After draining the acetone, he rinsed it with gas. The tank came out clean and shiny. Thanks for the tip Jerry.

Jerry recently bought a '37 Century Con-

vertible Coupe to restore. He purchased the car from Gary Stafford (#588) in Ventura, CA. Jerry says that dealing with Gary was a very pleasing experience. When he got the car home, he found it even bet-

ter than Gary represented it to be and that it's nice to deal with a person with integrity.

Sam Mahle (#1187) in Pennsylvania reports that he was a judge at a recent car show. One car there was a Rolls-Royce that the owner had just spent \$40,000 on in what was termed a "touch-up job!" \$7,000 of

this was spent on the motor alone. Sam says what the car really needed to be competitive was a through cleaning of the undercarriage to put it in equal condition with the rest of

the vehicles. As a result it did not do as well as some much lessor quality cars.

This bottom photo shows a most unusual 1938 Buick Van. It forms part of the car collection of Christopher Lee Willhans of

Insjon, Sweden. Exported from the US in 1938, this Buick chassis had built on it, by Oslo, Norway coachbuilder, N. Jacobsens, a very handsome delivery van body.





One-off Buick delivery was bodied by N Jacobsens of Oslo

It was ordered by a florist who, according to Christopher Lee. "wanted to deliver flowers in style." It was laid up during W.W.II and only has 42,000 miles on it. Presumably thought to be out of date. it became unused. Certainly it had not worn out and had no malfunction. The previ-

ous owner stored it for 15 years and the present one has not used it for at least ten.

This framed photo above shows the Brown Derby restaurant in Los Angeles with two Buicks in the foreground, a '37 Roadmaster and a 1940 sedan. Thanks to Andy Diem (#852) in Washington, DC for sharing this.

The middle photo shows a very attractive 36 Buick convertible. The photo was taken at

a movie studio in Hollywood with an aspiring actress. The car is painted a 1936 color called Francis Cream. Thanks to Gary Glazier (#1005) for sharing this with us.

You could order a '36 color on your '37 for an extra fee. Your firewall data plate would then have



SO. (for Special Order) stamped after the Paint No. for Francis Cream. (i.e. 424 50). This is what Lauren Matley (#47) is doing on his 1937 Special Convertible Coupe Model 46C. The #6 in the upper right corner means it's a "6 Wheel Job" or sidemounted car. (see bottom photo)


In the top photo (page 7) you can see what can happen if you don't keep lubricant in your

transmission. A tooth broke off one of the gears. This happened because a poor seal allowed transmission oil to flow through the torque tube to the rear end and the transmission ran dry.

When my wife and I were in Washington, DC several months ago, we visited **Von Hardesty** (#964) and his wife. Von even picked

us up in his 1937 Century Convertible Coupe. Last night I watched a Public Service Television (PBS) Nova Series program called "Top Gun Over Moscow." It was about the Soviet (now Russian) Air Force with several shots of Von commenting on the subject. Von is an expert on





the Soviet Air Force and has written several books on the subject. What a surprise to see one of our members on national television!

This bottom photo of a '38 Trunk Back 4-Door Sedan was taken in San Francisco in 1946 at the 22nd Annual Convention of the International Brotherhood of Electrical Workers. Charles Jekofsky (#524) in Washington, DC

sent this photo. He lives across the street from the Union's Training Center and often does

volunteer work there. Thanks C.J.

Congratulations go out to our Vancouver. Washington member Lauren Matley (#46) and his '29 Lincoln at the Pebble Beach Concourse (see photo at top of page 8). He won third place with 96.3 points. First and Second Place tied at 97.5 points. Lauren is selling the Lincoln to concentrate on finishing

his 37-46C Special Convertible Coupe.

The beautiful '38 Roadmaster with a Swedish Norberg body, shown on the right in the middle photo on page 8, belongs to member Mats Ahrin (#786) in

Nykoping, Sweden. The 1937 Special Sedan Model 41 belongs to a friend. The '37 is original inside and out except for a new paint job

in 1972.

Both Mats and his friend enjoy driving their Buicks. The Roadmaster was giving Mats some concern as it was burning oil and smoked a little.

The problem turned out to be a small hole in the dual-action fuel


pump's diaphragm. When the oil got hot and thin, oil drops came through the hole and went

> up the vacuum line to the intake manifold. That's why the car sometime had a puff of smoke come out the tail pipe. He replaced the fuel pump. Now his oil consumption is normal and the car does not smoke.


Member Mary Rhynard (#327) already

will take place in Saugatuck, Michigan, on Lake Michigan about 65 miles north of the Michigan-Indiana line and about 35 miles from Grand Rapids. Saugatuck is a well-known summer art colony. Mary has set it for June 6-7









and has most of a nice small motel reserved. (After mid-June the hotel rates along the Lakes go way up. Our cost will be in the \$75. range, but holding it later would have meant paying \$130. to \$150. per night).

Mary is hoping to arrange a tour of the Canadian Pacific passenger steamship "Keewatin," which is an Derek Hodgett (#690) sent this photo, at the top of page 9, of his parents and his 1937 Buick Limited. Derek's parents are both over 90 years old and are doing well. He took this photo to send to

From England,

relatives in Australia who have spotted a similar looking car in their town.



Indian word meaning northwest wind. It was

built in 1907 and retired in the 1960's. It's now a floating museum.

A company called Vintage Parts 411 has come out with a book on where to find Buick parts dealers, salvage yards and companies that repair and restore Buick parts. They say that with their new sourcebook, you can find any part for your old car. The book sells for \$12.75 plus \$2.00 shipping. If you're interested, contact them at:

Vintage Parts 411, 4909 Ruffner St., San Diego, CA. 92111. Phone (800) MOTORHEAD. Overseas call (619) 467-7140. These two Buicks (in the middle of page

9), a '55 Century 66S and a '37 Special Two Door Trunk Back Sedan Model 48 belong to **Howard Vaillancourt** (#440) in Guilford, CT. Howard also had a beautiful beige sidemounted '38 Century Coupe, but sold it last year. It now belongs to member **Tom Martindale** (#1198) in Santa Cruz, CA.

Don Micheletti (#250) phoned to tell me that after reading Wayne Yonce's (#1034) great tip about Modifying Your Trunk Lock in the last issue, he went out and did it. Now Don can open and close his

JUST ABOUT EVERY PLACE TO FIND JUST ABOUT EVERY PART FOR YOUR OLD

BUICK



Buick parts dealers, specialty salvage yards and companies that repair and restore Buick parts

Roadmaster's trunk without the key. Not being able open and close the trunk without using a key had annoved him in the past, but not anymore.

New member Harry Thompson

Sr. (#1232) in Greeley, CO. recently joined the Club. He has a '38 Century Sport Coupe which he has owned since 1962. It's a strong runner

and a good drag racer. He saw our address in the Buick Street Rod Association newsletter. Harry owns nearly 60 Buicks from 1938 on up. Plus he has tons of interior, engine, transmission and body parts for Buicks

from 1936 to 1955. Hopefully he'll advertise some of those items in the Torque Tube.





Harry also enrolled his son in the Club. He owns a '38 Special Sport Coupe Model 465. The Special has an overdrive in the tube torque which Harry says works well.

This 1938 Special Sport Coupe Model 46S, in the bottom photo, was driven to a local junk yard in 1956. And it's been sitting outside since

> then along with a '41 Buick Super Coupe. Now it has some rust but would make a good parts car. It's all original, and has the front bumper badge, jump seats etc. The original rims are inside the car. The car is just a

few miles from my home and was advertised





COVER CAR

Roadmaster WODY


By Jim Pascoe (#881) Escanaba, MI

n the list of ultimate body styles for the old car hobby one would have to include the venerable Woody Wagon. Everyone has their own favorite body style, but few will argue that the woody has become an icon that has stood the test of time.

This 1938 Roadmaster Woody Wagon shown here and on both the front and back cov-

ers was custom made by Jim Pascoe (#881) of Escanaba, MI.

"The woody was made from a Roadmaster 4-Door Sedan Model 81 parts car. I designed it in the style of late 1930's woodies. I cut the roof, doors, trunk and sides off leaving only the floor pan and the rear fenders."






"I designed the body using the original seats and the window mechanism. As you can see the front doors are hinged in the back in the style of early suicide doors. It has tan leather upholstery and a mahogany steering wheel. The rear windows are sliding like other woodies of the era."



"This photo shows the storage area behind the rear seat. A hatch in the floor raises to reveal another storage area underneath. That's handy for keeping things out of sight."



"Rear view of the woody with the BUICK 8 emblem fastened to the top of the tailgate. The car is all original except for the wood body. I am quite satisfied with it."

MY 30 BUIGN

By Roger Tollefsrud (#1200) - Mesa, AZ.


I have been a member of the Buick Club of America for over 15 years, but until recently never found the '38 I really wanted or the condition that suited me. But now I have!

This 1938 Buick Special 4-Door Trunk Back Sedan Model 41 was owned by a gentleman within 100 miles (160 km) of my home. He had owned it for 13 years and had a professional restoration, inside and out, done

to it recently. The color is Whistler (dark) Gray lacquer with Dante Red wheels.

We spend our winters here in Mesa, AZ., but come spring, we return to Spring Grove, Minnesota. Last year I brought my '39 Buick here and thoroughly enjoyed driving it during the beautiful winter months. I have since sold it after owning it for 19 years. Maybe next year I'll bring the '38.






This photo from the October 16, 1939 issue of **LIFE Magazine** shows US Ambassador to Poland Anthony Biddle Jr. (right) and an Embassy secretary. They and 19 other Americans of the Embassy staff are on a 250 mile flight from Warsaw to Rumania to escape the German Army's invasion of Poland at the start of W.W.H. The 21 Americans of the Embassy staff fled in seven cars and a truck. One of the cars was a 1938 Buick seen in the left of the photo with it's headlights covered to help protect against night attacks.



A street scene in Brooklyn, NY in 1950, by Arthur Zeipzig with two '38 Buicks. The one in the foreground has what looks like '41 accessory bumper ends (locally called elephant ears). The bumper has a license plate bolted to the center and is missing the two bumper guards. The fender parking lights have been replaced. This car has plaid seat covers and appears to be a Century sedan because it has a dark steering wheel. It is not a 80 or 90 Series because it does not have the chrome windshield reveal molding. The '38 in the upper part of the photo has an aftermarket center grille guard.



The bottom two photos on these pages came from the files of the US Dept. of Agriculture, Farm Security Administration. This one was taken in February, 1942 at Camp Crowder, Missouri. It's titled "Housing for construction workers" and shows a 1938 Buick Sedan, probably a Special.




Gary Stafford (#588) sent in this photo showing a street scene from long ago. The car on the right is a 1937 Buick 2-Door Sedan sporting a spotlight and a 1938 Accessory Grille Guard on the front bumper. Does any member know where this photo was taken? There are "Street Car" tracks in the street and overhead wires indicating there was some sort of electric transit system in place at the time this photo was taken. Los Angeles? We'll give you three cheers if you have the answer.



This photo titled "Loading baggage of train passenger into an automobile" was taken in September, 1940 in Montrose, Colorado. Again the car is a '38 Buick 4-Door Sedan. The car in front looks a bit like a '37 Buick Slant-Back Sedan. It is not as the gas filler cap is located on the body and not on the rear fender like a '37 Buick. Thanks to **Von Hardesty** (#964) for sharing these photos.

HOW THIS CLUB WAS FOUNDED



Dave Lewis (#237) founded the 1937-1938 Buick Club in 1980 in Springfield, Illinois. He developed an interest in these cars because his father found this 1937 Special Sedan abandoned on the street many years before. It even had a signed title certificate in the glove box. He then proceeded to have the car's paint stripped off and a new set of seat covers installed with the intention of having some fun driving it to work. When the body shop completed the enamel paint job, the car looked so good that every time he would park the car, kids would think it was a Hot Rod and try to raise the hood to check out the engine.

Well it took about one week to get the tops of the fenders scratch-up from the inexperienced kids playing with the hood. Dave's dad was so upset that he decided to put the car in storage for one of his sons to deal with later on.

That began a 25 year period of moving the car from one warehouse to another until the entire family was tired of pushing it. After Dave's father died, Dave inherited the car as this three brothers had no interest in it. Dave didn't have a big interest either, but a bunch of guys wanted the car to make it into a street rod. Dave didn't want this to happen out of memory for his father. So he decided to keep it.

The car was in pretty bad shape from having been moved around over the 25 year period and needed everything done just to get it running.

One thing led to another and Dave decided to restore it. Before long he was staring at a bare frame sitting on his garage floor. This was his first attempt at a complete restoration and it was kind of scary.

But Dave was hooked on Buicks and studied every book on the subject. It was during this time (1980) that he decided it would help if all of the 37/38 owners could get together and share their experiences and help each other find




parts. This was how the Club was born in 1980.

Dave finished his '37 at 3 AM the night before leaving for the Buick Nationals in Pennsylvania. This was a mistake. The car was about 99% complete with no road testing. When he arrived in PA. two days later, he found that the new clutch didn't work, the dash gauges paint buckled in the sun and the trunk ornament's paint rubbed through. He also found out that you can't clean and wax a car at 10 PM by the light from another car's headlights. So the moral

of the story is...check your car out 100% before taking it on a long trip and then having it judged.

After returning to Illinois he started preparing for the next show. He spent 37 hours detailing the car. He must have done something right as he won first place at the next five shows. Dave finally sold the car, but it's still in Springfield. The new owner hasn't been keeping the car up. So maybe someday Dave will buy it back and return it to its former glory. (This article to be continued).



CENTURY COUPES UNDER RESTORATION




This is the 1937 Century Coupe that Sam Mahle (#1187) in Pennsylvania drove while in college 35 years ago. Of course the Century looked and ran a lot better then. Sam sold it to a man who drove it some and then stored it for 30 years. He recently learned it was for sale and bought it back. Now he's starting to restore it. He'll get it to run first, then pull the engine for a later complete overhaul. Sam says he read recently that it's not recommended to rebuild the engine too far ahead of the need for it.

Then he'll remove the body and sandblast it. And also repair the suspension and clean the

gas tank. After that he'll see what needs to be rechromed. Good Luck on your restoration Sam!

Dave Tacheny (#997) in Minnesota recently bought this sidemounted 1938 Century Coupe. The rust free body is in primer and in excellent condition, but the car needs a total restoration. The original motor runs but smokes. It has the front bumper medallion and accessory grille guard. The trunk medallion is missing and it has an incorrect steering wheel. The running boards need new rubber. The grille is excellent and it has the jump seats. The original upholstery is bad as are the brakes. The firewall






ID tag indicates the car was originally Raphael (light) Green. It also came with the original air cleaner and extra parts including sidemount face plates and tread covers. And all the sidemount hardware is there. Dave is one of our biggest parts advertisers, so he should be in good shape for

most of the parts he'll need.

Dave is very happy with the car. He bought it sight unseen based on the owners description which turned out to be truthful and accurate. Good Luck on your restoration Dave. Keep us posted on how it's coming along.





FIREWALL DATA PLATES

By Harry Logan (#651)

Beginning in 1938, Buick identified where the car was assembled by the first digit of the *Frame Number*. "1" was Flint, Ml., "2" South Gate, CA., and "3" Linden, New Jersey. This number is on a plate riveted to the frame near the starter.

You can also tell where the car was assembled by looking at the **Firewall Data Plate**. If the

BODY NO. has only digits, it's a Flint car. If the BODY NO. is preceded by a "C", it's a South Gate. California assembled car. If the BODY NO. is preceded by an "L", it's a Linden, NJ assembled car. This is also true for '37 Buicks.

This tag, above, is for a South Gate assembled 1938 Century Sport Coupe Model 66S. In most cases, the

66S is stamped into the plate after the 1938 MOD., but not on this one. The TRIM No. is 408, Gray Bedford Cord. Someone has altered the original tag and

Cezanne Beige.

So '38 Buicks have two ways to identify the assembly plant and they should match. I have

So '38 Buicks have two ways to identify the assembly plant and they should match. I have seen cases where they don't. That means that one of the tags is incorrect, usually due to the car being rebodied. The data plates were originally painted body color, but now you often see


them silver because the paint has been removed from the aluminum plate.


On 1937 Buicks, the frame number does not identify the assembly plant, but the firewall data plate does.

So you can tell where your 1937 Buick was

assembled by looking at the Data Plate's BODY NO. This tag (bottom photo) is for a Flint as-

> Roadmaster Sedan Model 81 with sidemounted spares (6 stamped in upper right) and a mahogany dashboard (M stamped in lower right).





SHEDDING LIGHT ON COROT BEIGE



By Herb Sutton (#4) Roseburg, Oregon

My '38 Special Coupe is being painted the lightest standard color offered by Buick in 1938. It is number 522, Corot Beige. I found that the 1987 - 1996 Ford truck Light Chestnut to be a very close match. So far I've painted the body, rear fenders and trunk and am very satisfied with the color.

The PPG (formerly Ditzler) Delstar acrylic enamel Light Chestnut is #3956. The DuPont number is B8766-A. Because it is such a modern color, I'm sure it is available in the new paints approved for use in California.

In 1938 you usually had two choices for the wheels, either body color or an optional color. But there was only one correct wheel color for Corot Beige. That is Bugatti Red and it is available as DuPont enamel #20265-DH. This information was from an earlier article by **Thom Schuttish** (#6). The color is more of a brick red and goes quite well with Corot beige.

Nembers

William Tecco (#1218) 32571 Trailwood Ct. Solon, OH. 44139 37-66C

Leo Gilbert (#1219) 819 South G St. Port Angeles, WA. 98363 37-47

Vince Truant (#1220) 1537 Harmuth Road Lutherville, MD, 21093

Jim Woolsey (#1221) 1219 Roosevelt Escondido, CA. 92027 38-61

Doug Kennedy (#1222) 326 W. Oak Ave. El Segundo, CA. 90245 lan Milburn (#1223) Westend Dawnedge House Woburn Lane Aspley Guise, MK 17-8IH

Aspley Guise, MK 17 8JH England

38-41

Donald Glenn (#1224) 5964 Ford Rd.

3964 Fora Ra. Madison, OH. 44057 37-41

Leonard Beard (#1225) 3912 Montgomery Ct. Mt. Vernon, WA. 98247 38-46C

Mike Maroney (#1226) 426 East Valencia St. Apt. A Burbank, CA. 91501 38-61

Joseph Suarez (#1227) 438 E. 168th Place South Holland, IL 60473 37-468 Larry Wood (#1228) 68 Boehms Rd. W. Willow Street, PA. 17584

John Aylward (#1229) 321 13th Avenue N.W. Calgary, Alberta Canada T2M OE9 37-?

Bill Marsh (#1230) 337 Ridgeview Dr. Petaluma. CA 94952

Steve Sunseri (#1231) 8356 Gothic Ave. North Hills< CA. 91343 37-46

Harry C. Thompson III (#1232) 3331 Liverpool Fort Collins, CO. 80526 Harry C. Thompson II (#1233) 510 N. 11th Ave. Greeley, CO> 80631 38-66S

David Kissileff (#1234) 154 Lismore Ave. Glenside, PA. 19038 37-61

Richard Utecht (#1235) 833 Palamino Rd. Omaha, NE. 68154 38-46 38-46C

Joseph Conrey (#\$1236) 290 N. Orchard Ave. Vacaville, CA. 95688 38-41

Adrian Dearl.ing (#1237) c/o Post Office Prrompuraaw, QLD 4871 Australia, 38-66C

Parts FOR SALE

• 1937 PARTS	
Parking lights with pot metal	\$65.
Clock	\$25.
Gauges	
Rear Leaf Springs, used but good, 40/60 Series	
4-Door sedan body stainless including cowl small stainless	
Drivers side rear fenders, 40/60 Series	\$40
Generator, Big Series	\$50
Engine, Big Series	\$350
• 1937/1938 PARTS	
Map light switch, used	\$20
Buick Hose clamp set	
Rear window shade, used	
NOS Rocker arm shaft, with bushings, 40 Series	\$110 set
New car cover, never used, 40/60 Series	\$75
Front wing vents, 40/60 Series	
Hydraulic lifters, cam, rocker assembly, push rods etc., Big Serie	\$225 set
• 1938 PARTS	5
AAV-1 Carburetor, 40 Series	\$40
5 post regulator, used	
Transmission, 40 Series	
NOS cluster gear, 40 Series	
NOS Input or Pilot shaft, 40 Series	
Engine, Big Series	
All prices plus shipping. Call between 9 AM and 1 PM EST Monday to Fr	:1
and Sunday.	tady or anytime on Saturday
David Bylsma (#117)	
7802 Chevalier Ct.	
Severn, MD. 21144	
(410) 551-7236	
(410) 531-7236	
Parting 1937 & 1938 Specials and a 1937 Limited. The following is a p	nortion of parts available
Call with your needs.	witten of parts aranapic.
• 1937 PARTS	
Fender lights	\$65 pair
Trunk lights with good lenses.	\$50
Tail lights with lenses, all series	£50 pair
Wiper transmissions	\$50. pair
SPECIAL manifold	672
Throttle cable	
SPECIAL transmission	
SPECIAL transmission	
Two new Mood lower inner chafte for hughings	575.
Two new Moog lower inner shafts & bushings	
Rear view mirrors	S15.

Steering column support with ignition, keyed	\$35.
Map light switch	
Splash pans	
Rear motor mounts	\$15. pair
Headlight switches	
40 & 60 series doors	
Headlight bezels	
Radio grills	
Wiper motors	
Trunk support arms.	
Sun visors	
Steering sectors	
Bumper arms	
Bumpers	
CENTURY radiator	
Deluxe heater with defroster	
Deluxe heater	
Horn button	
Steering wheel	
Center stainless emblem	
After-market grille	
40/60 Running board brackets	
40/60 home-made sidemount cups & locks with keys	
80/90 bumpers	
80/90 bumper arms	
80/90 defroster ducts	
90 series rear brake drum	
90 series master cylinder	
90 series wheel cylinder	
80/90 rear motor mounts	
80/90 left side trunk hinge, pitted	\$15.
80/90 assist straps	\$20. pair
80/90 trunk support arm	
'37 LIMITED sidemount covers, very nice	
'37 80/90 sidemount cups	\$50. pair
'37 80/90 splash pans	
'37-'38 PARTS	
SPECIAL sidemount covers, complete & nice	5500, pair
SPECIAL running boards, solid & straight	
Headlight lenses	
SPECIAL exhaust valve body, working	\$50
NOS lower radiator hose, LARGE series	\$10 each \$25 for 3
1938 PARTS	
Deluxe heater with defroster	\$100
Right side grille	
734Z starter with solenoid	
1312 Starter with solehold	530.

(Parts For Sale continued from page 23)	
Horn buttons	\$10
LARGE SERIES air cleaner	
Radio hole plugs	\$15 set
Left headlight bucket with stainless, no rust	\$75
SPECIAL hood lettering	\$20 pair
Fender lights	\$75 pair
Defroster ducts	\$15 pair
Wiper transmissions	\$50 pair
Complete instrument cluster including water temp. but	1h e7=
Assist straps with screws	10
Clock with complete wire barness	
Clock with complete wire harness	\$25.
Cowl stainless trim, very nice	\$20. pair
Throttle cable	\$20.
Lighter, complete	\$15.
SPECIAL radiator	\$75.
Battery tray	\$20,
SPECIAL transmission	\$100.
Generator	\$50.
Manifold	\$75.
AAV-1 carb complete	\$125
Hood sides & tops	
SPECIAL rims	\$35
Rear license plate stand, bracket & light	
Bumper guards	\$25
Taillights, complete	\$65 pair
Dave Tacheny (#997)	
11949 Oregon Ave. N.	
Champlin, MN. 55316	
(612) 427-3460	
1938 SPECIAL PARTS	
REBUILT TRANSMISSION, Surfaced Flywheel, Rebuilt C	Clutch & Dick All B-11
Bellhousing, Fork, Throwout Bearing and Shifter	ciuten & Disk. All Balancea.
2 Front Brake Drums. Good Shape	
Oil Pan, Cleaned and Painted	\$50.
Valve Cover Clean Painted with Docal	\$25.
Valve Cover, Clean, Painted with Decal	\$20.
Distributor #1110801, cleaned & painted '38-'48	\$60.
Front Sway Bar	\$20.
Clock, works	\$40.
1937 Front Balancer with oil seal sleeve	\$20
1901 SUPER 263 Engine & Manual Transmission. New can	n bearings. 16 new valve guides &
new rings. Aluminum Pistons. Complete less Intake and Ca	ırb \$325.
SIROMBERG AAV 16 re-anodized and painted	
for '41-'47 Model 40-50. 7-66 #380106	
1979 vo TURBU ENGINES. 2 blocks (1 is .30 over), 2 cray	nks. 3 sets TRW Forged Pictors
Floated Rods, 6 cams, lots of overhead parts, 1 A/R TO4 &	1 stock Turbo, Intake & Ex-

(Parts For Sale continued from page 24)	
haust Manifolds, Turbo Q-Jet, lots of gaskets, Computer. This is a lot of parts Bill Savino (#915) 1530 Jill Jenee Lane Longwood, Fl 32779 (407)-682-7205	
• '37-'38 PARTS	
1937 CENTURY Engine, runs	5500.
1938 CENTURY left front fender	
3.9 rear end	
3.34 rear end	
• 1937 CALIFORNIA LICENSE PLATES Numbers cleared with DMV, good condition	
• 1937 PARTS Complete Front End Sheet Metal, both fenders, nosepiece and complete hood	
trim for a 1937 SPECIAL	
Two Headlight housings	
Front fender support	
Rear bumper bracket, right side only	\$ 10
Door hinges	15. pair
Emergency brake handle & assembly, no cable	
Right side tail light with lens bracket, NO LENS	
Left side tail light NO LENS OR LENS BRACKET	
Pair of trunk lid hinge brackets, U shaped part that bolts to lid of a coupe. Tory Recupito 3301 Florence Ave. Steger, IL. 60475	\$ 25
(708) 754-2697	

(Parts For Sale continued from page 25)	
• 1938 PARTS	
Horn Ring	\$ 25
Radiator for a Special	530
DeLuxe Heater w/defroster. Missing center trim	\$40
Battery cover	\$ 10
16" sidemount tread covers, no center trim	\$70
Paul Tegtmeier (#884)	
21 Kitzbuhel Rd.	
Parkton, MD 21120	
• '37-'38 PARTS	
Mint replated '38 SPECIAL hood center strip for the cost of the platin	g job \$100.
'37 SPECIAL 6 6 1	\$85
'37 SPECIAL front fenders (plain), good condition	\$50
'37 Front nose, good condition	\$50
'37 coupe rear window garnish molding	\$20
37 headiight buckets	\$40. pair
Karl Bosk (#1154)	
2211 So. 25 Ave., Escanaba, MI 49829 - (906) 786-2827	
• 1937 PARTS	
Radio, complete, very good face	\$120
Clocks	\$20 each
Heater, very good plastic	\$60
Used SPECIAL radiator	\$50
Water pump, NOS	\$25
Hub caps	\$50 50
Map light cover.	
Grille emblem	
Trunk license plate assembly, complete.	58.
Taillight lens, cover, cap	500.
Taillight lens, cap.	
Front fender parking lights, complete, very good	
Headlight buckets, very good	560. pair
• '37-'38 PARTS	\$40.
Special left Running Board, good core	
Transmission shift lever kit NOS	\$35.
Transmission shift lever kit, NOS	\$15.
Ignition assembly with key	\$25.
Muffler, NOS • 1938 PARTS	\$50.
Sales Brochure	\$75.
Owners Manual	\$30.
Used Special radiator	\$50,
SPECIAL Head complete with shaft and lifters	\$65.
Rear bumper (core)	620
Good used exhaust pipe, sandblasted and painted	\$25.
Front & rear inside reveal molding with good wood graining.	\$15

(Patrs For Sale continued from page 26)	
Front springs	\$40. pair
Rear Shocks, Delco, used	
Good used pressure plate for Special	
Grille, right, good used	
Grille, right, NOS	
Dash ash trays	
Rear seat ash tray	
Taillight, right and left, complete	
Taillight, lens only	
Air vent cover assembly	
Sun Visors, LARGE Series	
Battery frame	
Battery tray	
16" Wheels, blasted and in primer	\$25. each
16" Wheels with tires	
Left rear fender blasted and in primer, excellent	
Defroster ducts	
Trunk license plate assembly	
Hood handle	
Inside door handle	
Outside door handle	
Trunk handle	
Sedan trunk handle	
Hood ornament, good	
Cigar lighter	
Windshield washer dash plastic knob, good	
SPECIAL Engine, complete with carburetor, fuel pump etc. Runs go	
All Parts Plus Shipping	

Gerry Landry (#263)

(413) 592-2746 after 5 pm EST

Parts WANTED

WANTED:

2 - 1937 CENTURY Rims
 Chris Smith (#1216)

(310) 429-6822 PST

WANTED:

 Need Hood Top Center Stainless Molding For a1937 ROADMASTER 81-F.

Preston Turner (#718) 514 E. Main St.

Washington, N.C. 27889

(919) 946-6651

WANTED:

- Battery base and hold down strap
- Wheel jack
- Locking handle for 1938 CENTURY or SPECIAL Convertible Coupe Part No. 4082889 Section 12.247

Bill Whyte (#968)

Clerk's Acre

Lodgehill Road

Nairn, Scotland

IV12 45Z

EXTRA! EXTRA! BACK ISSUES NOW AVAILABLE

THE FOLLOWING BACK ISSUES ARE AVAILABLE FOR \$4.00 EACH POSTPAID.

- 1991-1992 VOLUME X NUMBERS 1 THROUGH 9
- 1992-1993 VOLUME XI NUMBERS 1, 2, 4, 5, 6 AND 7
 - 1993-1994 VOLUME XII NUMBERS 2, 4, 5 AND 6
- 1994-1995 VOLUME XIII NUMBERS 1 THROUGH 6
- 1995-1996 VOLUME XIV NUMBERS 2 THROUGH 6

Please make your checks payable to:

The 1937-1938 Buick Club 1005 Rilma Lane Los Altos, CA. 94022 USA

Parts WANTED

DESPERATELY NEED:

- 1938 SPECIAL or CENTURY Slant Back trunk lid in good condition.
- 1938 CENTURY emblem that mounts on the hood side panel.

Please help a fellow member out. I have many parts I can trade for these parts. Thanks.

David Bylsma (#117) 7802 Chevalier Ct. Severn, MD. 21144 (410) 551-7236

Matley Woodgraining Service

13912 S.E. 241st St. Kent, Washington 98042



Shop (206) 630-2008 Res. (206) 630-8887

"The Crowning Touch To A Quality Restoration"

Gars FOR SALE

FOR SALE:

 1937 Canadian-built SPECIAL Sedan.
 Older restoration of a good solid original car. Third owner. Have owned it for over 25 years.

\$7,500. U.S.

Don Zeldin RR#1 Woodville, Ontario Canada KOM 2TO (705) 439-2539

FOR SALE:

 1938 Buick SPECIAL 4 Door Trunkback Dual Sidemounts. Rebuilt original engine, transmission, rear and front end.
 New brakes and WWW tires. Interior restored including woodgraining and mat.
 New glass and all rubber. New wiring harness including blinkers. 37k miles showing which I believe is correct. Very nice driver. Drive her home.

\$16.300.

Bill Savino (#915) Longwood, Fl (Near Orlando & Disney) (407)682-7205





FOR SALE:

 1938 SPECIAL 4-Door Convertible Sedan. 60% restored. Many new parts.
 Excellent body with clear title. Located in Maryland. Delivery negotiable.

\$10,000.

David Bylsma (#117) 7802 Chevalier Ct. Severn, MD. 21144 (410) 551-7236

FOR SALE:

1938 SPECIAL 4-Door Sedan Model 41
Radio and heater. Dual sidemounts.
 4 new white wall tires, new clutch,
brakes, master cylinder. Re-cast steering
wheel. Car is green with tan interior.
 Many spare parts go with car
 \$7.800.

Dan Murtz (#835) 3400 Ralmark Ln. Glenview, IL 60025 (847) 6578038 after 7 pm

FOR SALE:

• 1937 Buick SPECIAL 4-Door Sedan. Original. Some rust.

\$2,800.00

(609) 965-6266 after 6 pm EST e-mail: mdak63A@prodigy.com (This ad sent in by Al McMichael (#319). Car is owned by a person in New Jersey.)

REPRODUCTION Parts FOR SALE

1936-1940 Sidemount nuts, all series	1.00 ea
1937-1963 Muffler clamp, straight eight\$	5.00 ea
1937-1938 Horn ring, chrome plated brass	90.00 ea
1937-1938 Horn ring, unplated brassS	65.00 ea
1937-1948 Firewall grommet (wiring harness) from engine to dash	
1937 Parking Light lens	
1938 Parking Light lens	0.00 pair
1934-1953 Series 40 Manifold gaskets	7.00 ea
1931-1953 Distributor Cap, 8 cylinder	8.00 ea
1931-1950 Distributor Rotor, 8 cylinder\$	4.00 ea
1937-1953 Point set, 8 cylinder\$	5.00 ea
ld 10% for shipping and handling Minimum chimping charge \$3.00	2000

Add 10% for shipping and handling. Minimum shipping charge \$3.00

Joe Krepps - 2486 Pacer Lane South, Cocoa, FL 32926-2606 • (407) 636-8777




onaldson Co.

2533 W. Cypress St. Phoenix, Arizona 85009 (602) 278-4505

Beautifyfully Recast STEERING WHEELS

Thru 1953 \$2.00 for Brochure, Must Specify Year







Running Board / Rocker Moldings

1934 thru 1940

SSAE for Information

BUICK RESTORATION SERVICES

P.O. BOX 442, PERRY,

MICHIGAN

48872



1953

HARNESSES

AUTHENTIC REPRODUCTION WIRING SYSTEMS THRU 1953 HAND CRAFTED WITH THE FINEST MATERIALS EACH SUPPLIED WITH: LIMITED WARRANTY INSTALLATION INSTRUCTIONS SCHEMATICS

ALSO OFFERING: WIRING SUPPLIES CATALOG OR INFORMATION \$5



FRONT FLOORMAT




)	B		B'	5
	AUTO	OMC	BIL	.IA
	(805)	434	4-29	63

1937-38 BUICK




1937-38	All	Models
Black o	B	rown
FF-378		\$195.

DOOR WEATH	ERSEAL-SPONGE	
Glue-in	DW-378	\$1.70 ft.
Clip-in	DW-80	\$3.40 ft.
	WC-80	
DOOR BOTTO	M SEAL	












HOOD	REST	PADS.	1937-38	6-8	Per	Car,	
	HR-	378				3.50) (



ς	SEAL For COUPES, 5/8" X 1"	
	SpongeTL-369	\$2.00 ft
	1/2'x1'x16' TL-1129	\$47.50



DASH GLASS. S	SILK-SCREE	NED on	
Back of GLASS	in COLORS	as	
Original.1937	SPEEDO	DG-37	.\$38.
	RADIO		
recovered	CLOCK	CG-37	\$28
1938	SPEEDO	DG-38	. \$38.

......RADIO.....RG-38.....\$23, CLOCK .. CG-38 \$28.



	and BRAKE PEDALS Series		
Black	CB-343BK	\$5.50	ea.
Brown		\$5.50	ea.

......FS-375.....\$12.50 pr.



PLASTIC	DASH KNOBS DK-37(38) \$	6
PLASTIC	DOOR HANDLE and Window	



1937	ONLY!	ACCELERATOR PEDALS	Series
	40-60	Back. AP-37BK	\$28.00
	Brown	AP-37BN	\$29.00

PEDAL FLOOR SEALS: All Models



PLASTIC DOOR !	d Window
Winder RINGS	\$6



SHIFT	BOOT, 1937-38 Series 40 Only)
	Black	\$ 9.75
	Brown	\$14.50



OUTSIDE DOOR HANDLE CHROME and RUBBER GROMMETS. 1 FERRULE & 1 GROMMET Per Set. 1938......DGF-380...........\$5 /Set



DOOR SILLS: Trim To Fit

Series 80-90 Black

2-Door \$62/pr. 2Door \$93/set.

GLOVE BOXES; \$27, ea.





PARKING LIGHT LENS...... \$17.50 ea

1938 TRUNK HANDLE/LIGHT MOUNTING SEAL DH-381\$8.75



STROMBERG...... CK-37XS \$26.00

TORQUE BALL SEAL KIT, All Models

MOTOR MOUNT, FRONT, All Models ROUND PADS SP-338 ... \$10. pr. MOUNT.......MM-347.. \$29. ea.



VISOR "VANIT!" MIRROR, VM-379 \$27, ea.

TBK-343\$26.00

TRUNK HINGES for 40-60, Chrome Plated \$150. pr.

LICENS	E PLATE FRAN	MES. Chromeo	Brass
	LF-333P	\$60. Pa	ir
FRONT	END PARTS F	or 40-60 Serie	is;



1937 HUB CAPS. All Ser HC-37	\$60.	ea.
WHEEL Beauty Rings. 15' or 16'	\$89.	/Set of 4
1937 or 38 HOOD ORNAMENT		\$85

FHON I END PARIS FOR	40-bu Series
Upper Outer Kit	\$39.00
King Pin Sets	\$35.50
Lower Inner Bushings	
Tie Rod End	\$27.00



SOME OTHER ITEMS WE STOCK; BEARINGS. DECALS, ENGINE PAINT, DECALS, SHOP MANUALS, PARTS BOOKS, BODY BOOKS and MORE SHIPPING;10% max.\$9. min. \$4. Prepaid, C.O.D. Add \$5.

BOB'S AUTOMOBILIA BOX 2119 ATASCADERO CA. 93423 TELEPHONE (805) 434-2963 .VISA- MASTERCARD-DISCOVER or C.O.D. CATALOG #43 \$4.00 - PHONE ORDERS - (Write For Catalog)



Buick Upholstery and Top Kits

Hampton Coach has been producing the finest quality interior and top products available for GM cars. We offer complete interiors, seat upholstery, tops and related components. Call our Inquiry Department today, toll free at 1-888-388-8726 and we'll be happy to discuss your Buick's needs.

HAMPTON


Phone 508-388-8047 (Gach) Fax 508-388-1113

P.O. Box 6, 6 Chestnut Street, Amesbury MA 01913

New for 1937-1938 BI



New stainless side mount emblems. Includes mounting screws on back side. \$62.50 each



New stainless convertible top latches & header hooks for 40 & 60 series Coupe & Phaeton (6 peice set) \$365.00



MAPLELEAF FABBRICATION & MACHINE

13912 SE 241st. Street, Kent, WA 98042 206-630-2008

© Torque Tube 1996-1997